



Access equipment 4th flr.



Looking out the southeast corner of 140 West Street.
DACS and Access equipment on the right.



DACS III & IV Spots on the lens are from dripping water from above. Note hole in wall At the end of the isle.



5ESS on the 7th floor in the southeast corner.



5ESS on 7th flr. Note fire hose in ladder at window.
Spots caused by water spraying around.